



# DC THERAPEUTIC REC LEAD WATER TEST RESULTS May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	DC THERAPEUTIC / TR CENTER	5/20/2016	WS- 011545	Utility	Basement	In boiler room (water source)	WT-042916-11562- A	2.2	WT-042916-11562- B	2.8				
2	DC THERAPEUTIC / TR CENTER	5/20/2016	WS- 011546	Cooler	1	In pool area	WT-042916-11563- A	< 2	WT-042916-11563- B	< 2				
3	DC THERAPEUTIC / TR CENTER	5/20/2016	WS- 011547	Cooler	1	In hallway lobby	WT-042916-11564- A	< 2	WT-042916-11564- B	< 2				
4	DC THERAPEUTIC / TR CENTER	5/20/2016	WS- 011548	Kitchen	1	In kitchen	WT-042916-11565- A	< 2	WT-042916-11565- B	< 2				
											Filter will be installed and then retested			
5	DC THERAPEUTIC / TR CENTER	5/20/2016	WS- 011549	Classroom	1	In activity room Left	WT-042916-11566- A	23.9	WT-042916-11566- B	3.4				
6	DC THERAPEUTIC / TR CENTER	5/20/2016	WS- 011550	Fountain	1	In activity room Right	WT-042916-11567- A	13.4	WT-042916-11567- B	6.9				
7	DC THERAPEUTIC / TR CENTER	5/20/2016	WS- 011551	Classroom	1	In senior building A	WT-042916-11568- A	< 2	WT-042916-11568- B	< 2				
8	DC THERAPEUTIC / TR CENTER	5/20/2016	WS- 011552	Classroom	1	In senior building side B	WT-042916-11569- A	< 2	WT-042916-11569- B	< 2				

**Footnotes:**

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.